Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 11/5/2014, 11/6/2014, 11/7/2014	Man Days: 3
Inspection Unit: North Shop	
Location of Audit: Chicago	
Exit Meeting Contact: Ted Lenart	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Steve Canestrini	
Company Representative to Receive Report: Tom Webb	
Company Representative's Email Address: TJWebb@peoplesgasdelivery.com	

	CONSTRUCTION INFORMATION			
Location of Construction:	Construction Performed By:			
6100 block of Bernice	Michels Constru	Michels Construction		
Contractor Foreman:				
Operator Inspector:				
	Person(s) On Job Site			
Jeff Hampson	Joe Fogel	James Dietrich		
Essa Maali	Harold Cunnigham	Phil Reiltz		
Dave Linze	Jerrad Ponce			
Description of Construction:				

MAIN INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.5]	Class location :	4
[192.619,192.621,192.623]	MAOP	25 PSIG
[192.63]	Pipe Size :	2"
[192.55,192.59]	Specification :	PE 2406/2708

Michels construction installing a 2" PE main via directional boring

[192.55,192.59]	5,192.59] Manufacturer :		
[192.55,192.59]	5,192.59] Pipe Grade :		
[192.55,192.59]	5,192.59] Wall Thickness :		
[192.63(a)(2)]	2.63(a)(2)] Are pipe, valves, and fittings properly marked for identification?		
General Comment:			
All pipe observed were properly marked.			
[192.227]	Date of Welder qualification:	Not Applicable	
General Comment:	<u> </u>		
PE main installation.			
[192.227]	Welder's Name:	Not Applicable	
General Comment:			
PE main installation.			
[192.225,192.275,192.277,192.279,192.28	Is pipe joined in accordance with approved written procedures?	Satisfactory	
General Comment:			
Observed the fusion operator perform a butt fusion of	on a 2" PE main. The operator followed the proper alignment, cleaning, fusing, and co	ool down procedures.	
[192.285]	Date of Plastic Joining Qualification :	6/12/14	
[192.285]	Joiner's name:	Phil Reiltz	
[192.455]	ls buried metallic pipe coated?		
General Comment:	<u> </u>		
PE main installation.			
[192.461]	Does coating meet 192.461?	Not Applicable	
General Comment:	<u> </u>		
PE main installation.			
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable	
General Comment:	<u> </u>		
PE main installation.			
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:		
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	Rectifier: No	
[192.461(c)]	ls coating inspected just prior to being installed in the ditch?		
General Comment:			
PE main installation.			

[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
PE main installation.		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		
All piping was installed below grade		
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
General Comment:		
Construction specifications were on	site, and available.	
[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
General Comment:		
A contract locator was on site to obs	erve that the specifications were being followed	
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	
General Comment:	<u> </u>	
The pipe was observed prior to insta	lling in the ditch. It could also be observed thru each opening where it crossed other facilities.	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
General Comment:		
The main was installed via directional	ll boring.	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
General Comment:		
The main was installed via directiona	l boring. Did not observe signs of stress being applied against the pipe.	
[192.321(e)]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
A tracer wire was installed with the n	nain. It was also checked for continuity once installed.	
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
General Comment:	-	
Observed assessation and viscous subse	e the pipe crossed other facilities. Required clearances were maintained.	

[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory	
General Comment:	· ·		
The main was approximately 38" in depth			
[192.503]	Are general testing requirements being met? Not Ch		
General Comment:	· · · · · · · · · · · · · · · · · · ·		
The pressure test was not being performed at this time	Э.		
[192.517]	Are records being made of strength and leak tests?	Not Checked	
General Comment:	· ·		
The pressure test was not being performed at this time	e.		
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory	
General Comment:			
Reviewed the OQ records of the employees on the job	site. All were qualified in the tasks assigned to them.		
[192.805(c)]	Were non-qualified personnel being directed and observed by a qualified individual?	Not Applicable	
General Comment:	· · · · · · · · · · · · · · · · · · ·		
All employees were qualified in the tasks assigned.			
[192.805(c)]	Were span of control limitations being followed?	Not Applicable	
General Comment:	· ·		
All employees were qualified in the tasks assigned.			
Was a Protocol 9 (Form 15) Completed?		No	
[192.614]	Were One Call Notifications performed as required?	Satisfactory	
General Comment:	· ·		
Reviewed the dig and permit for the job. Both were va	alid for the dates and locations of the excavation.		
[192.614]	Dig Ticket #	477244025	
[192.751]	Are adequate steps taken to minimize the potential for accidental ignition?		
General Comment:			
Fire extinguishers were present near locations of the o	construction or working equipment. In addition, warning signs were placed near the	e construction area.	
[192.719(b)]	Was each repair made by welding to a transmission line made in accordance with 192.713, 192.715, and 192.717 and examined in accordance with 192.241?		
General Comment:			

$\overline{}$			
ν μ	main	inctal	lation
_	manı	II ISLAI	ıauvı